



Calibration Specifications

Berries - Whole Fruit



MATERIAL

SUPPORTED RANGES OF BRIX

TEMPERATURE RANGE [°C/°F]

Strawberry

5.5-12.5 [°]

5-30 °C / 40-90 °F

Blueberry

7.5-17.5 [°]

5-30 °C / 40-90 °F

Raspberry

7-15.5 [°]

5-30 °C / 40-90 °F

Blackberry

6.5-18 [°]

5-30 °C / 40-90 °F

PARAMETER

REFERENCE DATA METHOD

Brix

Refractometer

